


ME260

Mechanical Engineering Design II

◆ Instructor notes

Metal Casting Fundamentals


- ◆ Definition of casting: pouring material in liquid form into a mold, where the mold has the shape of the part to be manufactured.
- ◆ Three steps involved:
 - 1- pouring of liquid material into mold
 - 2- allowing it to solidify
 - 3- removing the part from the mold



Just like
cake making

Metal Casting Fundamentals

- ◆ Melting/Solidification temperatures:
 - For a pure metal the melting/freezing temperature is clearly defined
 - For an alloy, solidification begins once temperature drops below T_L (the liquidus) and is complete when temperature reaches T_S (the solidus).
- ◆ The structure of the solidified metal/alloy depends on its composition and on the cooling rate.



The important thing to remember is that structure affects the mechanical properties

Fluidity of Molten Metal

- ◆ Viscosity: honey is more viscous than water.
- ◆ Surface tension: higher surface tension is not good for filling in sharp corners.
- ◆ Inclusions: such as dirt/sand in ingots. More inclusions means more viscosity and hence less fluidity



Fluidity



Fluidity




Fluidity








The better the fluidity, the easier it is to cast the metal into the mold

Casting Issues

- ◆ Solidification takes time $\propto C(\text{Volume}/\text{Surface area})^2$.
 C is a constant that depends on the mold and metal materials as well as temperature.



- ◆ Shrinkage: happens with cooling.
- ◆ Defects: surface discontinuities, cracking, and porosity (from shrinkage, gasses or both)




Classification of Casting Practices

- ◆ Expendable-Mold Casting Processes (sand casting, shell mold, plaster mold, ceramic mold, evaporative pattern, investment casting). → The mold is sacrificed/broken after every use
- ◆ Permanent-Mold Casting Processes. → The mold has repeated uses


Sand Casting

- ◆ Need two carved halves that are mated together.
- ◆ Refractory, meaning it can withstand high temperatures of molten metal.

(a)




(b) Metal poured here




Sand Mold Design

- ◆ Sprue to pour in the metal
- ◆ Vents to get rid of gasses.
- ◆ Risers to compensate for metal shrinkage during cooling.
- ◆ Cores to create cavities in a part




Evaporative-Pattern Casting (lost-foam process)

- ◆ Plastic is sacrificed.
- ◆ The pattern takes the shape of the final product. Need to replace every time.
- ◆ Can make complex shapes/details.




Investment Casting

- ◆ Can make multiple pieces simultaneously.
- ◆ Can produce good surface finish, close dimensional tolerances, and work for casting high-melting-point alloys.



Example of Permanent-Mold Casting



◆ Squeeze-casting.





◆ In Permanent-Mold Casting, the mold material is resistant to erosion and thermal fatigue (examples: cast iron, steel, bronze, graphite or refractory metal alloys).

Design Considerations in Casting

◆ Sharp corners are not recommended.




Poor




Good



◆ Avoid, as much as possible, hot spots and try to maintain uniform thickness.




Poor




Poor



Good



Good



Castability Tables

Castability Tables to choose a casting material.

Type of alloy	Application	Castability*	Weldability*	Machinability*
Aluminum	Pistons, clutch housings, intake manifolds	E	F	G-E
Copper	Pumps, valves, gear blanks, marine propellers	F-G	F	F-G
Ductile iron	Crankshafts, heavy-duty gears	G	D	G
Gray iron	Engine blocks, gears, brake disks and drums, machine bases	E	D	G
Magnesium	Crankcase, transmission housings	G-E	G	E
Malleable iron	Farm and construction machinery, heavy-duty bearings, railroad rolling stock	G	D	G
Nickel	Gas turbine blades, pump and valve components for chemical plants	F	F	F
Steel (carbon and low alloy)	Die blocks, heavy-duty gear blanks, aircraft undercarriage members, rail-road wheels	F	E	F
Steel (high alloy)	Gas turbine housings, pump and valve components, rock crusher jaws	F	E	F
White iron	Mill liners, shot blasting nozzles, railroad brake shoes, crushers and pulverizers	G	VP	VP
Zinc	Door handles, radiator grills,	E	D	E


*E, excellent; G, good; F, fair; VP, very poor; D, difficult.

Forming and Shaping Processes/Equipment

- ◆ Casting.
- ◆ Rolling (metals)
- ◆ Forging (metals)
- ◆ Extrusion and Drawing (metals)
- ◆ Sheet-metal Forming
- ◆ Metal-Powder Processing
- ◆ Glass and Ceramic Processing
- ◆ Forming and Shaping Plastics/Composites
- ◆ Rapid Prototyping
- ◆ Machining Operations

Rolling of Metals

- ◆ Similar to rolling dough in cooking or asphalt in street paving.






Roll or Rolling Force, F

◆ Needed to produce reduction in thickness.


◆ Can be reduced by:

- reducing friction (e.g. using lubrication)
- taking smaller reductions-per-pass to reduce the contact area
- rolling at elevated temperatures to lower the strength of the material
- applying tension to the strip



More on Rolling

- ◆ Flat-Rolling produces elongated grain structure immediately after a pass. Hot rolling can transform these elongated grains into finer, more equiaxed grain structure (good for material strength).



More on Rolling

◆ Two types of flat-rolling:

- Hot rolling

(Done at temperatures above the recrystallization temperature of the metal, e.g. 450°C for aluminum alloys, enhances ductility with fine grains)

- Cold rolling


(Done at room temperature, produces better surface finish, i.e. no scale, better dimensional tolerances, and stronger product, i.e. due to strain hardening)

◆ Roll material needs to be strong and resistant to wear

Example of Rolling Operations


◆ Shape or Profile Rolling e.g. to produce an I-beam

Stage 1




Blooming rolls

Stage 2




Edging rolls

Stage 3




Roughing horizontal
and vertical rolls

Stage 4




Intermediate horizontal
and vertical rolls

Stage 5



Edging rolls


Stage 6



Finishing horizontal
and vertical rolls

Forging of Metals

- ◆ Shaping a workpiece through compressive forces, or hammering, with the aid of dies and various tools.
- ◆ Old method to make coins, jewelry and swords.





Types of Forging Operations

- ◆ Open-Die Forging

- ◆ Closed-Die Forging

Examples of Open-Die Forging




Types of Forging Operations

- ◆ Open-Die Forging


- ◆ Closed-Die Forging

Examples of Closed-Die Forging: Note flash formation

Flash needs to be removed as a finishing operation




(a)




Making steel balls

Flashless or Precision Forging

◆ Be inventive in the die design




(a) Start of stroke



(b) End of stroke


Examples of Forging Operations

(a)



Coining

(a)



Heading,
for nail/rivet heads



Requirements for Die Material

- ◆ Strength at elevated temperatures
- ◆ Toughness at elevated temperatures
- ◆ Wear resistance

Examples of such materials are tool and die steels containing chromium, nickel, molybdenum and vanadium

Extrusion and Drawing of Metals

- ◆ Extrusion: *pushing* a metal through a die by force. The metal takes on the cross-sectional shape of the die
- ◆ Drawing: *pulling* a metal through a die by force. The metal takes on the cross-sectional shape of the die



Extrusion and Drawing of Metals





- ◆ Two types of Extrusion/Drawing:
 - Hot Extrusion/Drawing
 - Cold Extrusion/Drawing (room temperature)
- ◆ Extrusion/Drawing force can be reduced by using:
 - Lubricants (less friction)
 - Less extrusion/drawing ratio (A_0/A)
 - Higher temperatures
 - Lesser strong material to be extruded/drawn
- ◆ Die material should be strong and resistant to wear

Extrusion and Drawing of Metals

- ◆ Two types of Extrusion/Drawing:
 - Hot Extrusion/Drawing
 - Cold Extrusion/Drawing (room temperature)
- ◆ Extrusion/Drawing force can be reduced by using:
 - Lubricants (less friction)
 - Less extrusion/drawing ratio (A_0/A)
 - Higher temperatures
 - Lesser strong material to be extruded/drawn
- ◆ Die material should be strong and resistant to wear
- ◆ Surface cracking are some of the defects observed

Examples of Drawing Operations






◆ Tube-drawing operations



Sheet-Metal Forming/Working

- ◆ Any operations of thin/thick sheet metals to form them, i.e. change their shape and/or geometry
- ◆ Common operations are slitting (with scissors or snips) and punching (with a puncher)

Also called Shearing




This is similar to cutting cardboard


More on Sheet-Metal Forming/Working

- ◆ Maximum punch force: $F = 0.7TL(UTS)$, where T is the sheet thickness, L is the total length sheared (such as the perimeter of a hole), and UTS is the ultimate tensile strength of the material sheared
- ◆ Die material need to be hard and strong, and wear resistant. Lubrication helps prolong the life of the tool or die
- ◆ In shearing, it is important to reduce scrap or wasted material. See example below

OK






Better




Sheet-Metal Bending

- ◆ Figure illustrates the the bending operation
- ◆ Cracks can develop as a result of bending
- ◆ Springback can occur due to the elastic portion of the sheet deformation




Eliminating Springback





Various Bending Operations


(a) V die




(b) Wiping die



(a) Air bending




(b) Roll bending




(c) Bending in a 4-slide machine

Tube Bending


(a) Stretch bending



(b) Draw bending




(c) Compression bending




Explosive Forming

(a)




(b)



Processing of Metal Powders



- ◆ P/M stands for Powder Metallurgy
- ◆ Parts are made by compacting metal powder into a die and sintering.
- ◆ Sintering means heating the compacted/pressed particle mix to 70%-90% of the melting temperature. This allows the particles to bond or fuse permanently together.
- ◆ Main advantage of P/M process is near net-shape forming
- ◆ Main disadvantage is porosity which reduces strength

(c)





Example of parts made with a P/M process

Example of Compaction




Effect of Sintering

(a)





Neck formation
by diffusion




Distance between
particle centers
decreased, particles
bonded

(b)



Neck formation
by vapor phase
material transport






Particles bonded,
no shrinkage (center
distances constant)

Methods of Metal-Powder Production

- ◆ Atomization
- ◆ Mechanical Comminution (pulverization)
- ◆ Fine metal chips by machining
- ◆ Electrolytic deposition


Particle size vary depending on the method




Processing of Ceramics and Glass

- ◆ Crushed ceramics are mixed with a binder, e.g. clay, and are thus able to be formed in different shapes. This green mixture is dried and fired to achieve final hard touch. Finishing operations follow.
- ◆ Glass is made from raw material by mixing and heating in an oven to achieve a viscous fluid that can be shaped in different ways and then let to cool and harden.

Different Ceramic Shaping




Slip-casting a ceramic part




Jiggering operation

Glass Forming/Shaping

(b)




Making sheet glass



Making glass tube

Glass Forming/Shaping



Glass blowing