

Section-D

lecture-1

- ▣ Introduction:
- ▣ Computer aided design procedure:
- ▣ Calculation of Armature main Dimensions and flux for pole.
- ▣ Computer Program in MATLAB
- ▣ Sequential Steps for Design of Each Part and Programming Simultaneously.
- ▣ Design of Rotor
- ▣ Computer Output Results for Complete Design

Electric Machine

- ▣ Electric machines can be used as motors and generators
- ▣ Electric motor and generators are rotating energy transfer electromechanical motion devices.
- ▣ Electric motors convert electrical energy to mechanical energy
Generators convert mechanical energy to electrical energy


▣ Electric Machine

- ▣ Electric machines can be divided into 2 types:
- ▣ AC machines
- ▣ DC machines
- ▣ Several types DC machines
 - ▣ Separately excited
 - ▣ Separately excited
 - ▣ Shunt connected
 - ▣ Series connected
 - ▣ Compound connected
 - ▣ Permanent magnet

- ▣ Electric Machine
- ▣ All Electric machines have:
- ▣ Stationary members (stator)
- ▣ rotating members (rotor)
- ▣ Air gap which is separating stator and rotor
- ▣ The rotor and stator are coupled magnetically

DC Machines

- Schematic representation of a DC Machine




- ▣ Electric Machine

- ▣ The armature winding is placed in the rotor slot and connected to rotating commutator which rectifies the induced voltage
- ▣ The brushes which are connected to the armature winding, ride on commutator
- ▣ The brushes which are connected to the

- ▣ Electric Machine
- ▣ The armature winding consists of identical coils carried in slots that are uniformly distributed around the periphery of the rotor. Conventional DC machines are excited by direct current, in particular if a voltage-fed converter is used a dc voltage V_f is supplied to the stationary field winding
- ▣ Hence the excitation magnetic field is produced by the field


- ▣ Hence the excitation magnetic field is produced by the field coils. Due to the commutator, armature and field windings produce stationary magnetomotive forces that are displaced by 90 electrical degree.

Magnetic Flux in DC machines



DC Machines

- The current is induced in the **Rotor Winding** (i.e. the **Armature Winding**) since it is placed in the field (**Flux Lines**) of the Field Winding.




Orthogonality of Magnetic Fields in DC Machines

- mmf produced by the armature and mmf produced by the field winding are orthogonal.

$$\mathbf{F} = \mathbf{IL} \times \mathbf{B} = ILB \sin(90^\circ)$$

→ Magnetic field due to field winding


→ Magnetic field due to armature winding




DC Machines


- The force acting on the rotor, is expressed as

$$f = \underbrace{IL}_{\text{Due to the Armature}} \times \underbrace{B}_{\text{Due to the Field}}$$



- ▣ The Field winding is placed on the stator and the current (voltage) is induced in the rotor winding which is referred also as the armature winding.
- ▣ DC Machines
- ▣ In DC Machines, the mmf produced by the field winding and the mmf produced by the armature winding are at rightangle with respect to each other.
- ▣ The torque is produced from the interaction of these two fields.





Lecture-2

DC Motor

- ▣ The direct current (dc) machine can be used as a motor or as a generator.
- ▣ DC Machine is most often used for a motor. The major advantages of dc machines are The major advantages of dc machines are the easy speed and torque regulation.
- ▣ However, their application is limited to mills, mines and trains. As examples, trolleys and underground subway cars may use dc motors.
- ▣ In the past, automobiles were equipped with dc dynamos to charge their batteries.


- ▣ DC Motor Even today the starter is a series dc motor However, the recent development of power

electronics has reduced the use of dc motors and generator.

- ▣ The electronically controlled ac drives are gradually replacing the dc motor drives in factories.


- ▣ Nevertheless, a large number of dc motors are still used by industry and several thousand are sold annually

DC Machine Construction




DC Machines

- The stator of the dc motor has poles, which are excited by dc current to produce magnetic fields.
- In the neutral zone, in the middle between the poles, commutating poles are placed to reduce sparking of the commutator. The commutating poles are supplied by dc current.
- Compensating windings are mounted on the main poles. These short-circuited windings damp rotor oscillations. .




DC Machines

- The poles are mounted on an iron core that provides a closed magnetic circuit.
- The motor housing supports the iron core, the brushes and the bearings.
- The rotor has a ring-shaped laminated iron core with slots.
- Coils with several turns are placed in the slots. The distance between the two legs of the coil is about 180 electric degrees.




DC Machines

- The coils are connected in series through the commutator segments.
- The ends of each coil are connected to a commutator segment.
- The commutator consists of insulated copper segments mounted on an insulated tube.
- Two brushes are pressed to the commutator to permit current flow.
- The brushes are placed in the neutral zone, where the magnetic field is close to zero, to reduce arcing.




DC Machines

- The rotor has a ring-shaped laminated iron core with slots.
- The commutator consists of insulated copper segments mounted on an insulated tube.
- **Two brushes are pressed to the commutator to permit current flow.**
- The brushes are placed in the neutral zone, where the magnetic field is close to zero, to reduce arcing.




DC Machines

- The *commutator* switches the current from one rotor coil to the adjacent coil,
- The switching requires the interruption of the coil current.
- The sudden interruption of an inductive current generates high voltages .
- The high voltage produces flashover and arcing between the commutator segment and the brush.




DC Machine Construction




Commutator with the rotor coils connections.

DC Machine Construction




Details of the commutator of a dc motor.

DC Machine Construction




DC motor stator with poles visible.

DC Machine Construction



Rotor of a dc motor.

DC Machine Construction



Cutaway view of a dc motor.

1) Total Magnetic loading :-

The total amount of flux available at the air gap of the armature periphery is called Total magnetic loading. It is given by

$$p\phi = B_{av} \times \pi DL, \text{ wb}$$

2) Specific Magnetic loading:-

The total amount of flux available at the air gap of the armature periphery per unit area is called Specific Magnetic loading. It is given by

$$B_{av} = \frac{p\phi}{\pi DL}, \text{ wb/m}^2$$

1000 Avg. flux density

3) Total Electric loading :-

The total amount of ampere conductors available at the armature periphery is called Total Electric loading. It is given by

$$\boxed{I_z Z = ac \times \pi D}, \text{ A (or) AC}$$

A) Specific electric loading :-

The total amount of ampere conductors available at the armature periphery per unit length is called specific electric loading.

It is given by

$$ac = \frac{I_a \cdot Z}{\pi \cdot D}, \text{ A/m or AC/m}$$

POLE PITCH:


The peripheral distance measured between the centres of two adjacent poles is called pole pitch.

It is given by

$$\tau = \frac{\pi D}{p}, m$$

where, $D \rightarrow$ Dia. of machine, m

$p \rightarrow$ No. of poles.



SLOT PITCH:

(131)

The distance measured between the centres of two consecutive slots is called slot pitch. It is given


$$\text{by } \boxed{Y_s = W_t + W_s} \text{ cm}$$

Where, $W_t \rightarrow$ Width of tooth, cm

$W_s \rightarrow$ Width of slot, cm


Also the slot pitch can be expressed as given below.

$$\boxed{Y_s = \frac{\pi D}{s}} \text{ , cm}$$



Relation between avg. gap density and max. gap density :-

The flux density that is calculated over one pole pitch is called avg. gap density. It is denoted by B_{av} .



The Flux density that is calculated over one pole arc is called max. gap. density. It is denoted by B_g .

The relation is given by $B_{av} = \psi B_g = k_f B_g$

Where B_{av} = Avg. gap density
0.4 to 0.8 wb/m²

B_g = Max. gap density

Lecture-3

Field form factor (or) field form Co-efficient

It is defined as the ratio of avg. gap density to the max. gap density.

It is given by

$$K_f = \frac{B_{av}}{B_g}$$

, No unit

OUTPUT EQUATION :-

Let, P_a = Power developed by armature, kW

E = Emf induced in armature, V

I_a = Armature current, A

ϕ = Useful flux/pole, wb

Z = No. of armature conductors

n = Speed in r.p.s

N = Speed in r.p.m

p = No. of poles

a = No. of parallel path

I_z = Current per armature conductor, A

D = Dia. of armature, m

L = length of armature, m

B_{av} = ~~avg~~ Sp. Mag. loading, Wb/m²

a_c = Sp. elec. loading, ~~Wb/m²~~ A/m

∴ Power developed by armature, $P_a = E I_a \times 10^{-3}$ kW

But $E = \frac{\phi Z n p}{a}$ volt

where $n = \frac{N}{60}$ r.p.s

$$\therefore P_a = \left(\phi Z n \times \frac{P}{a} \right) \times \bar{I}_a \times 10^{-3} \text{ kW}$$

$$= (\phi \phi) \times \left(\frac{\bar{I}_a}{a} \times Z \right) \times n \times 10^{-3} \text{ kW}$$

$$= (\phi \phi) \times (\bar{I}_2 \times Z) \times n \times 10^{-3} \text{ kW}$$

where, $I_2 = \frac{I_a}{a}$ = Current per parallel path

$$= (B_{av} \times \pi D L) \times (ac \times \pi D) \times n \times 10^{-3} \text{ kW}$$

$$= (\pi^2 B_{av} ac \times 10^{-3}) \times D^2 L n \text{ kW}$$

$$P_a = C_c D^2 L n, \text{ kW}$$


Where, C_o is called output co-efficient of d.c. machine.

ref: / phys. up: $C_o = \pi^2 B_{av} a c \times 10^{-3}$ / over

NOTE :-

The fig. shows developed diagram of an armature wdg. The current per conductor is the same as current per parallel path.

$$\left[I_c = \frac{I_a}{a} \right], A$$



1) Volume of the machine related with B_{av} & a_c :

From output Eqn.

Volume of the machine is given by,

$$\boxed{D^2 L = \frac{P_a}{C_o n}}, m^3$$

For a given power rating, when volume of the machine decreases, both C_o and n are increased.

Voltage rating:

$$\overset{\uparrow}{a_c} = \frac{\overset{\uparrow}{I_2 Z}}{\pi D}, \quad \overset{\uparrow}{I_2 Z} \Rightarrow \overset{\uparrow}{I_2} \frac{\overset{\uparrow}{Z}}{2}, \quad \overset{\uparrow}{AT_a} \Rightarrow \overset{\uparrow}{AT_{fl}}, \quad \overset{\uparrow}{AT_{fl}} \Rightarrow \overset{\uparrow}{\Phi},$$

$$\overset{\uparrow}{\Phi} \Rightarrow \overset{\uparrow}{E}, \quad \overset{\uparrow}{E} \Rightarrow \overset{\uparrow}{V}$$

When a_c increases, the armature ampere turns pole increases. To overcome the effect of armature reaction, the field mmf has to be increased. Since field flux increases the induced emf becomes more and hence the terminal voltage increases. But high voltage requires more insulation and hence cost of insulation rises. So suitable value of a_c should be used.

Speed of machine:

$$ac \uparrow = \frac{I_2 Z}{\pi D \downarrow}, \quad D \downarrow \Rightarrow \text{Volume} \downarrow, \quad \text{Volume} \downarrow \Rightarrow \text{Speed} \uparrow,$$

$$\text{Speed} \uparrow = \text{Cooling} \uparrow$$

With higher value of ac , the dia. of armature decreases as the volume becomes less higher speed can be achieved. More air inside the machine results better cooling. Hence higher value of ac is preferable.

Size of machine:

$$ac \uparrow = \frac{I_2 Z}{\pi D \downarrow}, \quad D \downarrow \Rightarrow \text{Volume} \downarrow, \quad \text{Volume} \downarrow \Rightarrow \text{Size} \downarrow$$

When ac increases, the dia. of armature decreases since volume of machine decreases, the size becomes less and it results less cost. So value ac should be higher.

Show that

Copper loss $\propto \delta^2 PV$

Where $\delta =$

Proof :

$$\text{Copper loss} = I^2 R$$

$$= (\delta \times a)^2 \times \left(\frac{\rho l}{a}\right)$$

$$= \delta^2 P(al)$$

$$= \delta^2 PV$$

\therefore Copper loss $\propto \delta^2 PV$ if proportionality constant is unity

Lecture-4

- ▣ Choice of Specific Loadings
 - ▣ (i) Choice of specific magnetic loading
 - ▣ (II) Choice of specific electric loading
- Choice of specific magnetic loading
- (1) Teeth Flux density
 - (2) Frequency
 - (3) Voltage

- ▣ Teeth Flux density
- ▣ If flux density in the air gap is high, it may lead to high flux density in armature teeth beyond the maximum permissible limit.

- ▣ permissible limit.
- ▣ The maximum flux density in the teeth at minimum section should not go beyond 2.2 wb/meter square

- ▣ The reasons are obvious as higher flux density
- ▣ (i) Causes increased iron losses
- ▣ (ii) Requires higher ampere- turns for passing the flux through teeth leading to increased flux through teeth leading to increased field copper losses and increased cost of copper

- ▣ (2) Frequency

- ▣ The frequency of flux reversal in the armature is given by $f = np/120$

- ▣ The higher frequency will result in increased iron losses in the armature core and teeth. Therefore, there is a limitation in choosing higher B_{av} for a machine having higher frequency

Lecture-5

- ▣ (3) Voltage
- ▣ For high voltage machine, space required for insulation is comparatively more.
- ▣ Thus for a given diameter less space available for iron on the periphery leading to narrower teeth
Therefore, lower value of B_{av} has to be taken.
Otherwise teeth flux density increases beyond permissible limit

- ▣ Usually, B_{av} lies between 0.45 to 0.75 wb/square meter.
- ▣ The corresponding value of
- ▣ maximum flux density in the gap
- ▣ B_g varies from 0.64 to 1.1 Wb/m²

- ▣ Maximum flux density in the air gap $B_g = B_{av}K_f$
- ▣ K_f -Lower value of flux density for lower rating machines and higher values of flux density, for higher rating machines is the usual choice

- ▣ Choice of specific electric
- ▣ loading
- ▣ 1) Heating or Temperature Rise
- ▣ (2) Speed
- ▣ (3) Voltage
- ▣ (3) Voltage
- ▣ (4) Size of Machine
- ▣ (5) Armature Reaction
- ▣ 6) Commutation

- ▣ (1) Heating or Temperature Rise
- ▣ Using a high value of armature conductors (ac)
- ▣ creates problem of heat dissipation A high value of ac means either copper used is more i.e., having large number of conductors large number of coils obviously having increased insulation thickness leading to poor heat dissipation or diameter is less
- ▣ leading again to poor heat dissipation because of reduced surface area. Both of these results in high temperature rise in armature.

- ▣ (2) Speed

- ▣ For a high-speed machine, ventilation is obviously better and greater losses could be dissipated. Thus, a higher value of ' a_c ' can be used for higher speed machine.

Lecture-5

- ▣ 3) Voltage
- ▣ Machines with high voltage require large
- ▣ space for insulation Thus for a given diameter, it may not be possible to reduce the space required for iron because of the limitation imposed by flux density in the teeth Therefore, space for copper is reduced.
- ▣ So, lesser value of 'ac' is used in such cases.

- ▣ (4) Size of Machine
- ▣ In large size machine, there is more space for accommodating copper therefore higher ac should be used.
- ▣ (5) Armature Reaction With high value of ac, armature ampere turns also increases. Therefore armature reaction will be severe.
- ▣ To counter this, field mmf is increased and so the cost of machine goes high

- ▣ (6) Commutation
- ▣ High value of ac worsens the commutation condition in machines. From the point of view of commutation, a small value of ac is desirable.
- ▣ The value of ac usually lies between 15,000 to 50,000 amp. conductors /m

Advantage of having more number of poles

Weight of armature core and yoke is reduced

1. Cost of copper in the field and armature is reduced
2. Overall diameter and length of machine is reduced
3. Length of commutator is reduced
4. Distortion of field form is not excessive

Disadvantages of having more number of poles

1. Frequency of flux reversal is increased and causes more iron losses.
2. Labour charges are increased
3. Possibility of flash over between brush arms

Guiding Factors for selecting number of poles

The following may be taken as guiding factors for the choice of number of poles:

Guide lines for selecting for number of poles


1. Keep frequency of flux reversals in the armature between 25 to 50 Hz. Lower value of frequency is used for large machines is advisable.
2. The current per parallel path is limited to 200A. Thus the current per brush arm should not be more than 400 A.
3. The armature mmf should not be too large. The normal values of armature mmf per pole are listed in Table

Table ***Armature mmf per pole***

Output in KW	Armature mmf per pole (AT)
Upto 100	5000 or less
100 to 500	5000 to 7500
500 to 1500	7500 to 10000
Over 1500	Upto 12,500

4. If there are more than one choice for number of poles which satisfies the above three conditions, then choose the largest value for poles. This results in reduction in iron and copper.

Pole proportions :-



The cross-section of pole may be rectangular (or) square.

Length of pole, $L_p = b_p$ to $2b_p$

Breadth of pole, $b_p = (0.45 \text{ to } 0.55)\tau$

Now $L_p = 0.45\tau$ to 1.1τ
 $= (0.45 \text{ to } 1.1)\tau$

$$\therefore \boxed{\frac{L}{\tau} = 0.45 \text{ to } 1.1} \rightarrow \text{In general}$$

Case - I :

For rectangular pole face

$$\boxed{\frac{L}{\tau} = 0.7 \text{ to } 0.9}$$

Case - II :

For square pole face

$$\boxed{\frac{L}{\tau} = \psi} = 0.64 \text{ to } 0.72$$

Where, $\frac{L}{\tau} \rightarrow$ Ratio of core length to pole pitch

$\psi \rightarrow$ Ratio of pole arc to pole pitch.

NOTE:

$$\begin{aligned} 1) P_a &= P \left[\frac{1+2\eta}{3\eta} \right] \longrightarrow \textcircled{M} \longrightarrow P \leq 50 \text{ kW} \\ &= P \left[\frac{2+\eta}{3\eta} \right] \longrightarrow \textcircled{G} \longrightarrow P \leq 50 \text{ kW} \\ &= P \longrightarrow \textcircled{M} \longrightarrow P > 50 \text{ kW} \\ &= \frac{P}{\eta} \longrightarrow \textcircled{G} \longrightarrow P > 50 \text{ kW} \end{aligned} \quad \left. \begin{array}{l} \text{When } \eta_f \\ \text{is given} \end{array} \right\}$$

$$2) \left. \begin{aligned} P_a &= E_g I_a \times 10^3 \text{ kW} \longrightarrow \textcircled{G} \\ &= E_b I_a \times 10^3 \text{ kW} \longrightarrow \textcircled{M} \end{aligned} \right\} \text{From fundamentals}$$

$$3) E_g = V + I_a R_a \longrightarrow \textcircled{G}$$

$$E_b = V - I_a R_a \longrightarrow \textcircled{M}$$

$$4) I_a R_a = (x) \% \text{ of } V$$

$$5) I_a = I_L + I_f \longrightarrow \textcircled{G}$$

$$= I_L - I_f \longrightarrow \textcircled{M}$$

$$6) I_f = (x) \% \text{ of } I_L$$

$$7) I_L = \frac{\text{o/p in watts}}{V} \longrightarrow \textcircled{G}$$

$$= \frac{\text{i/p in watts}}{V} \longrightarrow \textcircled{M}$$

8) $I_a \leq 400A$, Assume lap or Wave ~~wound~~ winding
But wave winding is preferable.

$I_a > 400A$, Assume lap winding

9) Effect of series field winding is neglected.

$$10) l_g = \frac{AT_g}{800,000 K_g B_g}$$

Where, $K_g \rightarrow$ Gap contraction factor

$B_g \rightarrow$ Max. gap density

Armature Design

Mean emf induced per conductor $e_z = B_{av} L V_a$ (volt)

Peripheral speed $V_a = \pi D n$ m/sec.

Number of armature conductors

On full load, in case of generator, the emf induced in the armature winding exceeds the terminal voltage by an amount equal to the sum of the voltage drops in the armature winding, the interpole winding, the series winding and the contact drop at the brushes.

Thus, the generated emf in the armature.

$$E = V + I_a R_m \text{ for Generator} \quad \dots (2.25)$$

$$E = V - I_a R_m \text{ for Motor} \quad \dots (2.26)$$

Where V = Terminal voltage

$I_a R_m$ = Sum of Voltage drop in armature winding, interpole winding, series winding and Brush drop.

- * For 500V machines, $I_a R_m \simeq 2$ to $2\frac{1}{2}\%$ of Terminal voltage
- * For 250V machines, $I_a R_m \simeq 5$ to 10% of Terminal voltage

Thus number of conductors in series

$$Z_c = \frac{E}{\text{Mean emf per conductor}} = \frac{E}{e_c}$$

- * For a simplex lap winding (with single turn coil), Z_c represents total number of armature conductors per pole
(Since Number of Parallel Paths = Number of Poles)
- * For a simplex wave winding (with single turn coil), Z_c represents half the total number of conductors on the armature irrespective of number of poles (Since Number of parallel paths = 2)

2.6.2. Choice of armature winding

Simplex windings are normally used in comparison with multiplex windings because equalizer rings are used for multiplex windings which may make the machine costlier.

Simplex Lap Winding		Simplex Wave Winding	
1.	Number of parallel paths = Number of poles	1.	Number of parallel Paths=2
2.	Current in each path = $1/p$ of full load current	2.	Current in each path = half the full load current
3.	Each parallel path will develop an emf = E	3.	Each of the 2 paths will develop an emf = E
4.	Total number of armature conductors are large. Current per path is less. Therefore conductor cross sectional area is also reduced.	4.	Total number of armature conductors are less. Current per path is high. Therefore large cross sectional area is required.
5.	Equalizer connections are necessary which makes the machine costlier.	5.	No equalizer connections and less cost for machine.
6.	Normally used for large machines	6.	Normally used for small machines

Factors to be considered for choice of armature winding

- (i) Simplex lap winding is used for machines with current rating greater than 400A.
- (ii) Simplex wave winding is used for machines with current rating less than 400 A

Normally, single turn coils are used. If multi turn coils are to be used, maximum voltage between adjacent commutator segments should not exceed 28 to 30 volts.

Total number of conductors $Z = P * Z_c$ for simplex Lap Winding
 $= 2 * Z_c$ for simplex wave winding

Number of coils $= \frac{Z}{2}$ for single turn coils

$= \frac{Z}{2T_c}$ for multi turn coils

Where $T_c =$ Number of turns in one coil.

Choice of number of commutator segments

Number of commutator segments = Number of armature coils

Number of armature coils should always be checked as the number of commutator segments cannot exceed a certain limit.

Thickness of commutator segment at outer surface = 3 to 4 mm

Mica insulation between each segment \simeq 0.8mm

Pitch of commutator segment \simeq 4 to 5 mm

Commutator diameter $D_c \simeq (0.62 \text{ to } 0.75) D$ depending upon the voltage and rpm.

Commutator pitch = $\frac{\pi D_c}{C}$ should not be less than 4mm.

Where C = Number of commutator segments or armature coils.

Number of armature slots

The following factors are to be considered while selecting the number of armature slots.

(1) Flux Pulsations

Flux pulsations mean changes, in the air gap flux because of changes in the air gap reluctance between the pole faces and the irregularly shaped armature core surface under running condition. This flux pulsations give rise to eddy current losses in the pole-shoes and produce magnetic noise. The flux pulsations are reduced with increased number of armature slots.

(a) To avoid flux pulsations, the air gap reluctance per pair of poles should be practically constant which is possible if the number of slots per pair of poles is an odd integer i.e., the slots per pole is an integer plus $\frac{1}{2}$.

(b) To prevent the flux oscillations, the air gap reluctance under pole faces must be kept constant for all reactive positions of pole shoes and armature core. These conditions are approximated by

- (i) Properly chamfering the tips of pole faces.
- (ii) Making the number of slots per pole shoes an integer plus $\frac{1}{2}$

In actual design, the number of slots per pole arc should be an integer with slots per pole equal to an integer plus $\frac{1}{2}$.

Lecture-6

- ▣ Cooling
- ▣ For large of number slots, lesser number of
- ▣ conductors per slot. Therefore cooling is obviously
- ▣ better.
- ▣ (3) Tooth Width
- ▣ For large number of slots, the slot pitch reduces and also the tooth width. Two problem occurs by reduced tooth width.
- ▣ (i) Flux density at the minimum section of tooth increases causing increased iron losses
- ▣ (ii) It is difficult to support the teeth at the ventilating duct | without obstructing the ventilation

- ▣ 4Commutation |
- ▣ From commutation point of view, large number of slots smaller number of conductors per slot are better.
- ▣ (5) Cost A smaller number of slots are desirable
- ▣ considering the as the charges for punching the slots increase with their num' Further with smaller number of slots, there are fewer slots to insulate and therefore the cost of insulation also goes down

- ▣ Guiding factors for choice of number of armature slots
- ▣ (1) Slot Pitch The value of slot pitch lies between 20 to 40mm. The usual limit is between 25 to 35mm except in case of very small machines, where it may be 20mm and even less.
- ▣ (2) Slot Loading The slot loading i.e. number of ampere conductors per slot should not exceed about 15,000 A

- ▣ (3) Flux Pulsations
- ▣ The number of slots per pole pair should be an odd integer in order to minimize pulsation losses.
- ▣ (4) Commutation The number of slots per pole usually lies between 9 to 16 to prevent sparking.
- ▣ (5) Suitability for Winding When selecting number of slots, we must confirm that the number selected suits the armature windings. The number of slots per pole should match the value given in Table

Table **Number of Armature slots**

Rating (KW)	Slots per pole
Upto 5 KW	8
5 Kw to 50 KW	10
Above 50 KW	above 12

- ▣ Number of Armature Coils
- ▣ The number of turns per coil and the number of coils are so chosen that the voltage between commutator segments is limited to a value where there is no possibility of flashover. For very small machines, this limit may rise to 60V owing to their high internal resistance. Normally, the maximum voltage between adjacent segments at load should not exceed 30V.
- ▣ Average voltage between adjacent segments at no load

Dimensions of armature conductor

$$\text{Armature current } I_a = \frac{P_a}{E} * 1000$$

$$\text{Also } I_a = I_L + I_{sh} \text{ in case of generator}$$

$$= I_L - I_{sh} \text{ in case of motor}$$

Where I_L = Line Current in amperes.

I_{sh} = Shunt field current in amperes.

Now conductor Current $I_z = \frac{I_a}{a}$

\therefore Conductor cross section area $A_z = \frac{I_z}{\delta_z} \text{ mm}^2$

Where δ_z = Current density in armature conductors, A/mm^2

CHOICE OF CURRENT DENSITY

(a) $\delta_z = 4.5 \text{ A/mm}^2$, for large strap-wound armature with very good normal ventilation

(b) $\delta_z = 5 \text{ A/mm}^2$, for small wire-wound armature with very good normal ventilation

(c) $\delta_z = 6 \text{ to } 7 \text{ A/mm}^2$, for fairly high speed fan ventilated machine

Design of shunt field winding

Design Procedure

- (1) Assume a suitable depth d_f , for the winding from Table
- (2) Calculate the length of mean turn. The length of mean turn is $L_{mt} = 2(L_p + b_p) + 2d_f$...
- (3) In order to allow for voltage regulation, in generators assume that 15 to 20 percent of rated voltage is absorbed by the field rheostat.

∴ Voltage across the shunt field winding = (0.8 to 0.85) V
and voltage across each shunt field coil is

$$E_f = \frac{(0.8 \text{ to } 0.85)V}{p}$$

as there are as many shunt field coils as the number of poles and they are all connected in series.

(4) Resistance of each field coil $R_f = \frac{T_f \rho L_{mt}}{a_f} = \frac{E_f}{I_f}$

or area of shunt field conductor $a_f = \frac{I_f T_f \rho L_{mt}}{E_f} = \frac{AT_f \rho L_{mt}}{E_f}$

(5) Choose a suitable cross – section for the conductor. For small cross-section, standard round wire should be used. For larger cross-section, square or rectangular conductor should be used.

(6) Calculate the winding height

The space for winding along radial height is,

$$\begin{aligned}h_f &= h_{pl} - \text{height of pole shoe} - \text{insulation and clearance} \\ &= h_{pl} - (0.1 \text{ to } 0.2) h_{pl} - (0.1 \text{ to } 0.15) \tau\end{aligned}$$

(7) Number of turns provided $T_f = \frac{S_f h_f}{a_f} d_f$

Where S_f = space factor for the winding

= $0.8 (d/d_1)^2$ for round insulated conductor