



CNC Programming

Motivation and uses

To manufacture complex curved geometries in 2D or 3D was extremely expensive by mechanical means (which usually would require complex jigs to control the cutter motions)

Machining components with repeatable accuracy


Unmanned machining operations

Advantages of CNC

- Easier to program;
- Easy storage of existing programs;
- Easy to change a program
- Avoids human errors
- safer to operate
- Complex geometry is produced as cheaply as simple ones
- Usually generates closer tolerances than manual machines

Conventional milling machines

Vertical Milling machine architecture



Types of CNC machines

Based on Motion Type:

Point-to-Point or Continuous path

Based on Control Loops:

Open loop or Closed loop

Based on Power Supply:

Electric or Hydraulic or Pneumatic

Based on Positioning System

Incremental or Absolute

Basic CNC Principles

- Using a vertical mill machining center as an example, there are typically three linear axes of motion. Each is given an alphabetic designation or address. The machine table motion side to side is called the “X” axis. Table movement in and out is the “Y” axis, while head movement up and down the column is the “Z” axis.





Figure 8.7 Servo mechanism.

Servo drives are




- tolerant to tool cutting forces
- insensitive to load mass inertias (stiffness)
- insensitive to running friction forces
- linear to a high degree

Basic CNC Principles

Coordinates System



Consists of three axes positioned 90 degrees from each other.



Absolute Coordinate System

Incremental Coordinate System

Basic CNC Principles

All computer controlled machines are able to accurately and repeatedly control motion in various directions. Each of these directions of motion is called an axis. Depending on the machine type there are commonly two to five axes.

Additionally, a CNC axis may be either a linear axis in which movement is in a straight line, or a rotary axis with motion following a circular path.




Figure 6.2 Coordinate systems used in NC: (a) for flat and prismatic work and (b) for rotational work. (On most turning machines, the z-axis is horizontal rather than vertical as we have shown it.)

Basic CNC Principles

If a rotary table is added to the machine table, then the fourth axis is designated the "b" axis.




Figure 6.11 (a) Four-axis CNC horizontal milling machine with safety panels installed and (b) with safety panels removed to show typical axis configuration for the horizontal spindle.

How CNC Works

- Controlled by G and M codes.
- These are number values and co-ordinates.
- Each number or code is assigned to a particular operation.
- Typed in manually to CAD by machine operators.
- G&M codes are automatically generated by the computer software.

Features of CNC Machinery

- The tool or material moves.
- Tools can operate in 1-5 axes.
- Larger machines have a machine control unit (MCU) which manages operations.
- Movement is controlled by a motors (actuators).
- Feedback is provided by sensors (transducers)
- Tool magazines are used to change tools automatically.

Tools

- Most are made from high speed steel (HSS), tungsten carbide or ceramics.
- Tools are designed to direct waste away from the material.
- Some tools need coolant such as oil to protect the tool and work.





Tool Paths, Cutting and Plotting Motions

- Tool paths describes the route the cutting tool takes.
- Motion can be described as point to point, straight cutting or contouring.
- Speeds are the rate at which the tool operates e.g. rpm.
- Feeds are the rate at which the cutting tool and work piece move in relation to each other.
- Feeds and speeds are determined by cutting depth, material and quality of finish needed. e.g. harder materials need slower feeds and speeds.
- Roughing cuts remove larger amounts of material than finishing cuts.
- Rapid traversing allows the tool or work piece to move rapidly when no machining is taking place.

Manual NC programming

Part program: A computer program to specify

- Which tool should be loaded on the machine spindle;
- What are the cutting conditions (speed, feed, coolant ON/OFF etc)
- The start point and end point of a motion segment
- how to move the tool with respect to the machine.

Standard Part programming language: RS 274-D (Gerber, GN-code)

History of CNC

The RS274-D is a **word address format**

Each line of program == 1 **block**

Each block is composed of several instructions, or (**words**)

Sequence and format of words:

N3 G2 X+1.4 Y+1.4 Z+1.4 I1.4 J1.4 K1.4 F3.2 S4 T4 M2

sequence no

destination coordinates

dist to center of circle

feed rate


spindle speed

tool

preparatory function

Other function

Manual Part Programming Example





Tool size = 0.25 inch,
Feed rate = 6 inch per minute,
Cutting speed = 300 rpm,
Tool start position: 2.0, 2.0
Programming in inches



Motion of tool:

p0 → p1 → p2 → p3 → p4 → p5 → p1 → p0


1. Set up the programming parameters




2. Set up the machining conditions



3. Move tool from p0 to p1 in straight line



4. Cut profile from p1 to p2



Linear interpolation

target coordinates


```
N040 G01 X3.875 Y9.125
```

or


```
N040 G01 Y9.125
```

X-coordinate does not change → no need to program it

5. Cut profile from p2 to p3



6. Cut along circle from p3 to p4




circular interpolation, CCW motion

target coordinates


```
N060 G03 X7.366 Y9.125 I6.5 J9.0
```

coordinates of center of circle



7. Cut from p4 to p5



8. Cut from p5 to p1



9. Return to home position, stop program



CNC Programming Basics

- CNC instructions are called part program commands.
- When running, a part program is interpreted one command line at a time until all lines are completed.
- Commands, which are also referred to as blocks, are made up of words which each begin with a letter address and end with a numerical value.

CNC Programming Basics

- Each letter address relates to a specific machine function. “G” and “M” letter addresses are two of the most common. A “G” letter specifies certain machine preparations such as inch or metric modes, or absolutes versus incremental modes.
- A “M” letter specifies miscellaneous machine functions and work like on/off switches for coolant flow, tool changing, or spindle rotation. Other letter addresses are used to direct a wide variety of other machine commands.

CNC programming

Important things to know:

- Coordinate System
- Units, incremental or absolute positioning
- Coordinates: X,Y,Z, RX,RY,RZ
- Feed rate and spindle speed
- Coolant Control: On/Off, Flood, Mist
- Tool Control: Tool and tool parameters

CNC programming

- Programming consists of a series of instructions in form of letter codes
- Preparatory Codes:
 - G codes- Initial machining setup and establishing operating conditions
 - N codes- specify program line number to executed by the MCU
- Axis Codes: X,Y,Z - Used to specify motion of the slide along X, Y, Z direction
- Feed and Speed Codes: F and S- Specify feed and spindle speed
- Tool codes: T – specify tool number
- Miscellaneous codes – M codes For coolant control and other activities

Programming Key Letters

- O - Program number (Used for program identification)
- N - Sequence number (Used for line identification)
- G - Preparatory function
- X - X axis designation
- Y - Y axis designation
- Z - Z axis designation
- R - Radius designation
- F – Feed rate designation
- S - Spindle speed designation
- H - Tool length offset designation
- D - Tool radius offset designation
- T - Tool Designation
- M - Miscellaneous function

Explanation of commonly used G codes

- G00 – Preparatory code to control final position of the tool and not concerned with the path that is followed in arriving at the final destination.
- G01 – Tool is required to move in a straight line connecting current position and final position. Used for tool movement without any machining- point to point control. (linear interpolation)
- G02 – Tool path followed is along an arc specified by I, J and K codes.(circular interpolation)

Table of Important G codes

G00 Rapid Transverse

G01 Linear Interpolation

G02 Circular Interpolation, CW

G03 Circular Interpolation, CCW

G17 XY Plane,G18 XZ Plane,G19 YZ Plane

G20/G70 Inch units

G21/G71 Metric Units

G40 Cutter compensation cancel

G41 Cutter compensation left

G42 Cutter compensation right

G43 Tool length compensation (plus)

G43 Tool length compensation (plus)

G44 Tool length compensation (minus)

G49 Tool length compensation cancel

G80 Cancel canned cycles

G81 Drilling cycle

G82 Counter boring cycle

G83 Deep hole drilling cycle

G90 Absolute positioning

Table of Important M codes

- M00 Program stop
- M01 Optional program stop
- M02 Program end
- M03 Spindle on clockwise
- M04 Spindle on counterclockwise
- M05 Spindle stop
- M06 Tool change
- M08 Coolant on
- M09 Coolant off
- M10 Clamps on
- M11 Clamps off
- M30 Program stop, reset to start

Program Command Parameters

Optimum machine programming requires consideration of certain machine operating parameters including:

- Positioning control
- Compensations
- Special machine features

Positioning control is the ability to program tool and machine slide movement simultaneously along two or more axes. Positioning may be for point-to-point movement or for contouring movement along a continuous path. Contouring requires tool movement along multiple axes simultaneously. This movement is referred to as "Interpolation" which is the process of calculating intermediate values between specific points along a programmed path and outputting those values as a precise motion. Interpolation may be linear having just a start and end point along a straight line, or circular which requires an end point, a center and a direction around the arc.



Rules for programming

Block Format

N135 G01 X1.0 Y1.0 Z0.125 F5


Sample Block

- Restrictions on CNC blocks
- Each may contain only one tool move
- Each may contain any number of non-tool move G-codes
- Each may contain only one feed rate
- Each may contain only one specified tool or spindle speed
- The block numbers should be sequential
- Both the program start flag and the program number must be independent of all other commands (on separate lines)
- The data within a block should follow the sequence shown in the above sample block


APT Programming Example

Cylindrical Part


Raw Material



Finished Part



APT Programming Example (*Cylindrical Part*)



O0013

N0005 G53

N0010 T0303

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

N0070 G57 G00 X22.50 Z2.0 S500

N0080 G01 Z-30.0 F100

N0090 G00 X23.0 Z2.0 S500

N0100 G84 X17.5 Z-20.0 D0=200 D2=200 D3=650

N0110 G00 Z2.0

N0120 X50.0 Z50.0

N0130 M30



APT Program Interpretation

00013

Program identification number

APT Program Interpretation

O0013

N0005 G53

To cancel any previous working zero point



APT Program Interpretation

O0013

N0005 G53

N0010 T0303

N0010 Sequence number

T0303 Select tool number 303

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.0 Z0.0 S500 M04

G57 To set the working zero point as saved


G00 Rapid movement (no cutting)

X26.0 X location (as a diameter; 13 form zero)

Z0.0 Z location

S500 Spindle speed is 500 rpm

M04 Rotate spindle counterclockwise



APT Program Interpretation

O0013

N0005 G53

N0010 T0404


N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

G01 Linear interpolation (cutting)

**X-0.20 Move only in x direction until you pass
the center by 0.1 mm (facing)**

F100 Set feed rate to 100 mm/min.



APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

G00 Move rapidly away from work piece (no cutting)

Z2.0 the movement is 2 mm away from the face.

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

Go to a safe location away from the workpiece [x = 50 (25 from zero), z = 50] to change the tool.

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

T0404 Select tool number 404

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

N0070 G57 G00 X22.50 Z2.0 S500

G57 PS0

G00 Rapid movement (no cutting)

X22.50 X location (as a diameter; 11.25 form zero)

Z2.0 Z location

S500 Spindle speed is 500 rpm

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404


N0070 G57 G00 X25.00 Z2.0 S500 M04

N0080 G01 Z-30.0 F100

G01 Linear interpolation (cutting)

Z-30 Move only in z direction (external turning)

F100 Set feed rate to 100 mm/min.



APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

N0070 G57 G00 X25.00 Z2.0 S500 M04

N0080 G01 X22.5 Z-70.0 F100

N0090 G00 X23.0 Z2.0 S500

G00 Move rapidly away from work piece (no cutting) to location x= 23.0 (11.50 from zero) and z = 2.0.

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

N0070 G57 G00 X25.00 Z2.0 S500 M04

N0080 G01 X22.5 Z-70.0 F100

N0090 G00 X26.0 Z2.0 S500

N0100 G84 X17.5 Z-20.0 D0=200 D2=200 D3=650


G84 Turning cycle for machining the step

X17.5 final diameter

Z-20 length of step is 20 mm

D0=200 Finish allowance in X direction (0.2 mm) D2=200 Finish allowance in Z direction (0.2 mm)

D3=650 Depth of cut in each pass (0.65 mm)



APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

N0070 G57 G00 X25.00 Z2.0 S500 M04

N0080 G01 X22.5 Z-70.0 F100

N0090 G00 X26.0 Z2.0 S500

N0100 G84 X17.5 Z-20.0 D₀=200 D₂=200 D₃=650

N0110 G00 Z2.0

G00 Move rapidly away from workpiece (no cutting)

Z2.0 the movement is 2 mm away from the face.

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

N0070 G57 G00 X25.00 Z2.0 S500 M04

N0080 G01 X22.5 Z-70.0 F100

N0090 G00 X26.0 Z2.0 S500

N0100 G84 X17.5 Z-20.0 D₀=200 D₂=200 D₃=650

N0110 G00 Z2.0

N0120 X50.0 Z50.0

X50.0 Z50.0 Move to the tool changing location

APT Program Interpretation

O0013

N0005 G53

N0010 T0404

N0020 G57 G00 X26.00 Z0.0 S500 M04

N0030 G01 X-0.20 F100

N0040 G00 Z2.0

N0050 X50.0 Z50.0

N0060 T0404

N0070 G57 G00 X25.00 Z2.0 S500 M04

N0080 G01 X22.5 Z-70.0 F100

N0090 G00 X26.0 Z2.0 S500

N0100 G84 X17.5 Z-20.0 D₀=200 D₂=200 D₃=650

N0110 G00 Z2.0


N0120 X50.0 Z50.0 T00

N0130 M30


M30 Program End

Programming Example


Raw Material



Finished Part



Programming Example



G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75


N009 G01 X0 Y0 Z-0.5 XYFeed 75

N010 G81 R3 E9 N7 Z-0.5

N011 M05

N012 M02

Programming Example



Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

N012 G01 X50 Y45 Z10 ZFeed 150


N013 M05

N014 M02

Program Interpretation

G55 X200 Y80

Setting the datum to the lower left corner of the work piece





Program Interpretation

G55 X200 Y80

Program 1

Program Identification Number



Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N001 Sequence Number

**M06 Tool Change (End Mill with
Diameter=12mm)**

T1 Tool Number

Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

**Start rotating the spindle clockwise with 400
rpm**



Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

Go to Safe Position with feed 150mm/min

Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

Lower the end mill to determine the depth of cut

Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

**Move from the lower left corner
of the work piece to the right
lower one cutting with
feed=75mm/min**



Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400


N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

Move from the lower left corner of the work piece to the right lower one cutting with feed=75mm/min



Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150


N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

**Cutting the horizontally up to
X=30**



Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150


N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75

Cutting to X=0 & Y=40



Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75


N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75

N009 G01 X0 Y0 Z-0.5 XYFeed 75

Complete the counterling



Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75

N009 G01 X0 Y0 Z-0.5 XYFeed 75

N010 G81 R3 E9 N7 Z-0.5

**Repeat 7 times blocks from N003 to N009
with incremental offset of Z=-0.5**

Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75

N009 G01 X0 Y0 Z-0.5 XYFeed 75

N010 G81 R3 E9 N7 Z-0.5

N011 M05

Spindle Off

Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X-8 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75

N009 G01 X0 Y0 Z-0.5 XYFeed 75

N010 G81 R3 E9 N7 Z-0.5

N011 M05

N012 M02

End Program



Program Interpretation

Tool Change


Changing the tool

Program Interpretation

Tool Change

G55 X200 Y80

Setting the datum to the lower left corner of the work piece





Program Interpretation

Tool Change

G55 X200 Y80

Program 2

Program Identification Number

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N001 Sequence Number

M06 Tool Change (Drill with

Diameter=6mm

T2 Tool Number



Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

**Start rotating the spindle clockwise with 400
rpm**



Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

Go to Safe Position with feed 150mm/min

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

Stop above the center of the first hole

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400


N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150

ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

Start Drill the first hole



Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

Retract to a position above the hole

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

Stop above the center of the second hole

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

**N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed
150**


N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

Drill the second hole



Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

Retract to a position above the second hole

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

Stop above the center of the third hole

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150


N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

Drill the third hole



Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

N012 G01 X50 Y45 Z10 ZFeed 150

Retract to a position above the third hole

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

N012 G01 X50 Y45 Z10 ZFeed 150

N013 M05

Spindle off

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

N012 G01 X50 Y45 Z10 ZFeed 150

N013 M05

N014 M02

End Program

Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

N012 G01 X50 Y45 Z10 ZFeed 150

N013 M05

N014 M02

End Program

CAD/CAM

Two computer-based systems which impact the use of CNC technology are computer aided design and computer aided manufacturing.

A computer aided design, or CAD, system uses computers to graphically create product designs and models. These designs can be reviewed, revised, and refined for optimum end use and application. Once finalized, the CAD design is then exported to a computer aided manufacturing, or CAM, system.


CAM systems assist in all phases of manufacturing a product, including process planning, production planning, machining, scheduling, management and quality control.

Automatic Part Programming


Software programs can automatic generation of CNC data




Define Tool




CNC data



Make 3D model




Simulate cutting



Automatic part programming and DNC

Very complex part shapes → very large NC program

NC controller memory may not handle HUGE part program



Summary

CNC machines allow precise and repeatable control in machining

CNC lathes, Milling machines, etc. are all controlled by NC programs

NC programs can be generated manually, automatically

Additional references: RS274D code descriptions