LECTURE 2

3.2 OVERVIEW OF SINGLE PHASE IM

- Types of 1\(\phi \) induction Motor
 - Split Phase Motor
 - Capacitor Start Motors
 - Capacitor Start, Capacitor Run
 - Shaded Pole Induction Motor
 - Universal Motor (ac series motors)

3 OVERVIEW OF 3 PHASE IM

- Simple and rugged construction
- Low cost and minimum maintenance
- High reliability and sufficiently high efficiency
- The speed is frequency dependent
 - > not easily to control the speed
 - → thanks to power e

3 OVERVIEW OF SINGLE PHASE IM

 can be part of a pump or fan, or connected to some other form of mechanical equipment such as a winder, conveyor, or mixer.

